



1404 Oxford - no erosion controls across entrance; considerable sediment in the street



1206 Garner - gap in silt fence; while mulch may prevent soil under it from eroding, it is not contain runoff from upgradient



1813 Treadwell - sediment control screen on storm drain inlet is clogged and needs cleaned



1819 Treadwell - no controls at the lowest corner on the lot allows sediment to escape; erosion channel readily visible



1300 Folts - silt fence not maintained; gap readily visible



1300 Folts - sediment control screen on storm drain inlet is clogged and needs cleaned



1811 Ashby - no controls; LDC § 25-8-181 requires controls to remain in place until permanent revegetation has been established



1811 Ashby - sediment deposited in gutter just downstream of construction site