

MISCELLANEOUS SITES (photos taken 24 Apr 2019)



1811 Collier

No erosion controls. Pile of sand sitting along curb. Sand and mud has washed into street and down gutter.



1912 Paramount

No controls between privacy fence and curb. Exposed bare dirt between fence and curb washes into street.



2014 Rundell

No controls over much of the front. Crushed mulch socks do little to stop sediment from leaving site.



2018 Rundell

No erosion controls at all. Sediment is flowing into street.



1401 Rabb

Major gaps in controls that do exist. Flattened mulch socks do little to stop sediment from leaving site.



2019 Ashby

Gap between silt fence and mulch sock. Runoff leaves the site between silt fence and mulch sock.